

Rubber looks shot.
Replacement recommended?
Are these just remnants of rubber boots?
Was able to free up shaft movement w/ Kroil.
Any specific lubrication recommended?
Is this piece removable?
Necessary to remove?