



12828 Bel-Red Rd
Bellevue, WA 98005
425-455-0407

Store: 419
Invoice: 41900598835
Salesperson: Michael T

Work Order #: 41900598688

Customer Information

Customer ID: 373-15021
Name: MATT CHESTNUT
Address: 4636 190TH AVE SE
City, State, Zip: ISSAQUAH, WA 98027
Phone: (206) 972-3006

Vehicle Information

Vehicle: 2001 TOYOTA LAND CRUISER
Color: BLACK
Mileage: 222,894
License: BHG7785

Les Schwab Invoice

Qty	Product Code	Product Description	Price/ea	FET	Amount
2	147687	BR50 BEARING SET	\$46.99	\$0.00	\$93.98
1	13692	PACK WHEEL BEARINGS - 4 WHEEL DRIVE	\$194.99	\$0.00	\$194.99
2	496964	T08139 CV AXLE	\$169.60	\$0.00	\$339.20
2	210198	JLM506849A BEARING	\$63.24	\$0.00	\$126.48
2	13697	MISC SHOP RATE PER HOUR	\$139.99	\$0.00	\$279.98
1	13579	THRUST ANGLE ALIGNMENT - DOMESTIC/IMPORT CARS, PICKUPS, VANS	\$109.99	\$0.00	\$109.99
2	210195	JLM506810 BEARING	\$37.06	\$0.00	\$74.12
2	265784	710456 WHEEL SEAL	\$21.86	\$0.00	\$43.72

Parts Subtotal: \$677.50
Labor Subtotal: \$584.96
Sales Tax: \$127.51
Tire Fee: \$0.00

Invoice Total: \$1,389.97

Payment Method:

VISA Approval# 05150D Card# XXXXXXXXXXXX4662

\$1,389.97

Wheel Position: LF, RF, TORQUED BY JAY

Service Checklist:

Visual Tire Inspection | Comments: 8/32ND TREAD

Tire Pressure Check | Comments: 32

Visual Wheel Alignment | Comments: ADJUSTED FRONT TOE

Front End Component Check | Comments: REPLACED FRONT CV AXLES, REPLACED FRONT INNER AND OUTER BEARINGS AND SEALS

Visual Shock/Strut Inspection | Comments: APPEAR OEM NO LEAKS

Visual Brake Inspection | Comments: FRONT BRAKES 7MM