

My LX 03 Sowner / 2003 LX470



Service History for VIN: JTJHT00W233535149

Sort By:

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	07/15/2015		139663	0816682	ENGINE MINOR C/S PLEASE CHECK OVER ENTIRE VEHICLE FOR CUSTOMER TO PURCHASE - CUSTOMER THINKS TAC DOES NOT WORK PLEASE CHECK - ALSO CHECK A/C DOESN'T SEEM TO BLOW COLD - FOUND CODE C1340 OPEN CIRCUIT IN CENTER DIFF - FOUND A/C NO WORKING - LOOKS LIKE IT MAY HAVE JUST BEEN CHARGED AND LEAKED OUT - BOTH FRONT AXLES LEAKING - COOLANT LOW POSSIBLE WATER PUMP LEAK - TIMING BELT/DRIVE BELT DUE EBRAKE FROZEN - SHOCKS VERY RUSTED - NEE
Dealer Reported	07/15/2015		139663	0816682	*TOYOTA QUALITY INSP CUSTOMER REQUESTS TOYOTA QUALITY INSPECTION C/S PLEASE CHECK TO SEE IF NEW TIMING BELT STICKER WAS PUT ON - DOES NOT KNOW IF BELT WAS DONE - PERFORMED INSPECTION AS PER REQUEST
Dealer Reported	07/15/2015		139663	0816682	AIR CONDITIONING
Dealer Reported	08/09/2011	<u>Motorworld Lexus</u>	74412	0066623	LEXUS LOANER PROGRAM AN \$80.00 LATE FEE MAY BE APPLIED IF THIS VEHICLE IS NOT RETURNED WITHIN 24 HOURS OF NOTIFICATION OF COMPLETION. NOTE; MUST BE 21 - HAVE A VALID DRIVER'S LICENSE - AND PROOF OF INSURANCE.
Dealer Reported	08/09/2011	<u>Motorworld Lexus</u>	74412	0066623	COURTESY INSPECTION - 74412 MAINT. DUE
Dealer Reported	08/09/2011	<u>Motorworld Lexus</u>	74412	0066623	ALF INSTALL STEERING FITTING KIT & SUPPORT KIT LX 470 - CUSTOMER STATES ALF RECALL NEEDED - RECALL - 74412 ALF SSC PERFORM ALF STEERING SHAFT SSC. 0523G1 (1.9 HRS)
Dealer Reported	08/09/2011	<u>Motorworld Lexus</u>	74412	0066623	
Dealer Reported	07/18/2009	<u>Rav Catena Lexus of Monmouth</u>	41165	0469341	40000 MILE SERVICE NON WARRANTYNON OEM - CUSTOMER REQUESTS 40000 MILE SERVICE REPLACE ENGINE OIL & FILTER. INSPECT TIRE PRESSURE & TIRE WEAR.ROTATE TIRES/SET PRESSURES.CHECK/REPLENISH FLUIDS. INSPECT ENGINE DRIVE BELTS & HOSE. INSPECT AIR FILTER. INSPECT BRAKE PADS, DISC, LINES & HOSES. INSPECT - ===== - 40000 MILE SERVICE PERFORMED
Dealer Reported	01/19/2009	<u>Rav Catena Lexus of Monmouth</u>	32824	0443087	30000 MILE SERVICE NON WARRANTY CUSTOMER REQUEST 30,000 MILE MAINTENANCE SERVICE LX470 2003 AND PRIOR YEARS.REPLACE ENGINE OIL AND FILTER. PERFORM 4 WHEEL ROAD FORCE WHEEL BALANCE AND ROTATE. CHECK TIRES FOR WEAR,SET TIRE PRESSURES INCLUDING SPARE TIRE RESET TIRE PRESSURE WARNING SYSTEM - ===== - 30000 MILE SERVICE PERFORMED
Dealer Reported	01/19/2009	<u>Rav Catena Lexus of Monmouth</u>	32824	0443087	NAVIGATION COMPUTER CUSTOMER REQUESTS TO HAVE THE NAV UPDATED. PARTS HAS DISC IN STOCK 1/8/09. PLEASE CHECK AND ADVISE ===== CLIENT STATES AT TIMES THE SYSTEM GETS LOST PLEASE CHECK THE FUNCTION OF THE NAV

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					SYSTEM - TECH INSTALLED A NEW NAVIGATION UPDATE DISC AS REQUESTED
Dealer Reported	01/19/2009	Ray Catena Lexus of Monmouth	32824	0443087	DISTRIBUTOR/HDLIGHT/T. SGNL CLIENT STATES THERE IS A LIGHT OUT ON THE FRONT END, CHECK ALL LIGHTS - TECH REPLACED THE LEFT FRONT FOG LIGHT BULB
Dealer Reported	01/19/2009	Ray Catena Lexus of Monmouth	32824	0443087	ACCESSORY REPLACE THE BATTERY IN THE KEY - TECH REPLACED THE BATTERY IN THE KEY
Dealer Reported	01/19/2009	Ray Catena Lexus of Monmouth	32824	0443087	BATTERY/COIL SPK PLUG TECH STATES THE VEHICLE BATTERY FAILED THE LOAD TEST - TECH REPLACED THE VEHICLE BATTERY
Dealer Reported	01/19/2009	Ray Catena Lexus of Monmouth	32824	0443087	WINDSHIELD WIPER/WASHER TECH STATES THE DRIVERS SIDE WIPER ARM IS TOO LONG - TECH REPLACED THE DRIVERS SIDE WIPER ARM
Dealer Reported	09/17/2008	Ray Catena Lexus of Monmouth	27341	0425728	NAVIGATION COMPUTER CUSTOMER STATES NAVIGATION ISN'T WORKING/PLEASE CHECK AND ADVISE - TECH REMOVED AND CLEANED THE NAVIGATION DISC TO REMEDY
Dealer Reported	09/17/2008	Ray Catena Lexus of Monmouth	27341	0425728	ACCESSORY CLIENT ORDERED A NEW CD MAGAZINE - INSTALL - TECH INSTALLED THE CD MAGAZINE
Dealer Reported	07/07/2008	Hoffman Lexus	26502	0101585	COMPLET AUTOQUAL
Dealer Reported	06/25/2008	Hoffman Lexus	26502	0100438	CERTIFIED PREOWNED PDI - CERTIFIED PRE - OWNED PDI - 26502 200 PERFORMED CERTIFIED PRE - OWNED PDI SERVICE.CAR HAS L/F BUMPER DAMAGE,DIRTY SEAT BELTS,AND FLOOR MATS.
Dealer Reported	06/25/2008	Hoffman Lexus	26502	0100438	30K 30,000 MILE SERVICE - 26502 490 30K SERVICE.REPLACE CABIN AIR FILTER.
Dealer Reported	06/25/2008	Hoffman Lexus	26502	0100438	REPLACE REAR BRAKE PADS AND MACHINE ROTORS - 26502 250 REPLACE REAR PADS AND MACHINED ROTORS.
Dealer Reported	06/25/2008	Hoffman Lexus	26502	0100438	REPLACED PASS SIDE SUNVISOR LIGHT INOP - 26502 PASS SIDE SUNVISOR HARNESS HAS SHORT. 30 REPLACE PASS SIDE SUNVISOR
Dealer Reported	06/25/2008	Hoffman Lexus	26502	0100438	SEE LINE D SUNVISOR LOOSE
Dealer Reported	06/25/2008	Hoffman Lexus	26502	0100438	MATS IN CARGO AREA MATS - 26502 PUT LARGE MAT IN REAR OF TRUCK.
Dealer Reported	04/24/2008	Hoffman Lexus	25488	0097758	ADV CUST UNABLE TO DUPLICATE CONCERN AT THIS TIME. C/S THERE IS A WIRE BURNING ODOR FROM THE ENGINE COMPARTMENT AFTER BLOWER MOTOR REPLACEMENT - 25488 CHECK FOR BURNING SMELL - COULD FIND NO BURNING SMELL.
Dealer Reported	02/09/2008	Hoffman Lexus	24386	0094017	LUBE, OIL AND FILTER CHANGE, TOP OFF ALL FLUIDS AND RECHECK TIRE PRESSURES - 24386 .4 LOF BRAKES @ 5/5MM TIRES @ 8/8 32NDS
Dealer Reported	02/09/2008	Hoffman Lexus	24386	0094017	RADIO SPEAKER ASSY, REAR #2 CUSTOMER STATES THERE IS A SPEAKER THATS SOUNDS POOR - SPEAKER COVER CRACKED - 24386 SPEAKER SOUND IS DISTORTED. 860551 T1 - 72 T2 - 71 FPN 86160 - 0W270 .4 REPLACE SUB WOOFER
Dealer Reported	02/09/2008	Hoffman Lexus	24386	0094017	BLOWER MOTOR ASSEMBLY CUSTOMER STATES THE BLOWER MOTOR FAN IS NOISEY - SOP - BLOWER MOTOR IS NOISEY - 24386 BLOWER IS NOISEY 870151 T1 - 71 T2 - 71 FPN 87103 - 60250 .3 REPLACE BLOWER MOTOR
Dealer Reported	02/09/2008	Hoffman Lexus	24386	0094017	WARR INFO 6176916 Y7H 03/18/2004 03/18/2011 000100000 BAGOT REYNOLD - 24386
Dealer Reported	01/24/2008	Hoffman Lexus	24239	0093354	OPERATING AS DESIGNRD AT THIS TIME C/S LEFT REAR SPEAKER FEELS LIKE ITS BLOWN - 24239 SPEAKERS WORK AS DESIGNED
Dealer Reported	01/24/2008	Hoffman Lexus	24239	0093354	OK DOFU - 2/2/04 - 24239
Dealer Reported	01/24/2008	Hoffman Lexus	24239	0093354	LUBRICATE DRIVE SHAFT C/S AT TAKE OFF IT FEELS LIKE THERE IS SOMETHING LOOSE

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					UNDERNEATH VEH - 24239 LUBRICATE DRIVE SHAFT AND INSPECT SUSPENSION.
Dealer Reported	01/24/2008	Hoffman Lexus	24239	0093354	ROAD TEST VEHICLE FOR CUSTOMER CONCERN - 24239
Dealer Reported	01/24/2008	Hoffman Lexus	24239	0093354	OK TOP ALL FLUIDS - 24239 TOP OFF FLUIDS
Dealer Reported	01/24/2008	Hoffman Lexus	24239	0093354	SPECIAL ORDER PART CUSTOMER STATES TO CHECK HVAC BLOWER MOTOR IS NOISEY - 24239 ORDER A NEW BLOWER MOTOR.
Dealer Reported	08/09/2005	Hoffman Lexus	10057	0047777	10K LOF, TOP OFF FLUIDS. INSPECT: AIR FILT, BATT, WIPERS, EXH SYS, STRG WHEEL FR 10K LOF, TOP OFF FLUIDS. INSPECT: AIR FILT, BATT, WIPERS, EXH SYS, STRG WHEEL FREE PLAY/LINKAGE, SUSP, BALL JTS & DUST CVRS, DRIVSHFT BOOTS, FRNT/REAR BRAKE PADS/DISCS, BRAKE LINES & MSTR CYL. ROTATE & BALANCE TIRES. ROAD TEST. WASH & VAC. - 10057 3 1.0 LOF R&B TIRES
Dealer Reported	08/09/2005	Hoffman Lexus	10057	0047777	TYPE IN DESCRIPTION CK NAV SEEMS TO OPERATE DIFFERENT SINCE SSC, MAYBE IN WRONG REGION..PLEASE CK MAP - 10057
Dealer Reported	07/21/2005	Hoffman Lexus	9734	0046875	5LB INSTALL DRL KIT MY0305 LX470 (SSC) - SSC 5LB - DRL - SSC 5LB - 9734 RUNNING LIGHT CAMPAIGN 5520E2 1.1 PERFORMED BULLITEN
Dealer Reported	07/21/2005	Hoffman Lexus	9734	0046875	OTHERS ADJUST C/S THERE IS A RATTLING COMING FROM DRIVER FRONT WINDOW - OUT OF ALIGNMENT - 9734 WINDOW COMING OUT OF REGULATOR 675994 /T1 - 9A /T2 - 57 /FP#69802 - 60070 .9 REPLACED REGULATOR BOLTS REPAIR THREADS
Dealer Reported	08/27/2004	Hoffman Lexus	4778	0032667	5,000 MILE SERVICE - MAINTENANCE - 4778 .6 5K
Dealer Reported	03/01/2004	Hoffman Lexus	1913	0025201	INSTALL DVD JO - DIS TO INSTALL DVD
Dealer Reported	02/27/2004	Hoffman Lexus	1901	0025168	COLORTEK TO REPAIR
Dealer Reported	02/18/2004	Hoffman Lexus	85	0024176	OTHERS R&R* C/S WINDOW NOISE FROM PASS WINDOW - DOOR NOT SEATING PROPERLY - 1883 670991 2.4 67001 - 60600 T1 - 59 T2 - 57 ADJUST WINDOW GASKET, ADJUST DOOR GASKET, DOOR WONT SEAT PROPERLY(STRAIGHTEN DOOR FRAME). TEST DRIVE AND AIR LEAK APPEARS TO BE GONE
Dealer Reported	02/18/2004	Hoffman Lexus	85	0024176	TYPE IN DESCRIPTION PASS SIDE LEATHER IS TORN - 83
Dealer Reported	02/18/2004	Hoffman Lexus	85	0024176	UNABLE TO DUPLICATE CONCERN AT THIS TIME C/S DASH RATTLE OVER CENTER CONSOLE BY WIPERS - 1883 NO NOISE HEARD DURING TEST DRIVE W/ TODD P.
Dealer Reported	01/14/2004	Hoffman Lexus	82	0023487	BALANCE ALL FOUR WHEELS VIBRATION ON HYWAY - VIBRATION ON HYWAY TIRES OUT OF BALANCE BALANCE ALL 4 TIRES - 1180 TIRES OUT OF BALANCE 042214 042214A - A - A T1 - 44 T2 - 42 1.5 BALANCE 4 TIRES/WHEELS
Dealer Reported	01/14/2004	Hoffman Lexus	82	0023487	1,000 MILE SERVICE - 1180 1K .4 1K SERVICE
Dealer Reported	12/29/2003	Hoffman Lexus	14	0022922	INSTALL SPOILER - 14 2.0 INSTALL SPOILER
Dealer Reported	08/06/2003	Hoffman Lexus	1	0107814	

Information Accuracy

Information presented on this Web site is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus dealership that conducted the service and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein "as is" without warranty of any kind.

Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer

CPO Owner Information

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site but will not be shared with future owners of the vehicle.

Owner-Reported Information and Privacy Terms

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this Web site, please [click here](#).