



**Torfab**  
 2902 W Marine View Drive  
 Everett, WA 98201  
 (206) 659-8677  
 info@torfab.com  
 www.torfab.com

# Inspection #4487

Zach Harrison

1999 Toyota Land Cruiser Base

Mobile: (206) 659-5123  
 zachharrison17@gmail.com

## Test Drive

	Item	Green	Yellow	Red
1	Hubs Lock			
	<b>Note/Recommendation:</b>			
2	4WD Engage	✓		
	<b>Note/Recommendation:</b>			
3	4WD Low	✓		
	<b>Note/Recommendation:</b>			
4	Lockers			
	<b>Note/Recommendation:</b>			
5	Brake Feel	✓		
	<b>Note/Recommendation:</b>			
6	Engine Feel	✓		
	<b>Note/Recommendation:</b>			
7	Steering Feel (Vibrations or Play)	✓		
	<b>Note/Recommendation:</b>			
8	All Exterior lights	✓		
	<b>Note/Recommendation:</b>			
9	Horn	✓		
	<b>Note/Recommendation:</b>			
10	Interior Systems (windows, lights, gauges)	✓		
	<b>Note/Recommendation:</b>			
11			✓	
	<b>Note/Recommendation:</b> Sliders are contacting the body causing the rattle. Both sides.			



Torfab  
 2902 W Marine View Drive  
 Everett, WA 98201  
 (206) 659-8677  
 info@torfab.com  
 www.torfab.com

# Inspection #4487



Totals

8

1

0

## Cooling System

Item	Green	Yellow	Red
1 Coolant Condition / Color	✓		
Note/Recommendation: <i>red</i>			
2 Radiator tank condition		✓	
Note/Recommendation: <i>discolored</i>			
3 Radiator Hoses	✓		
Note/Recommendation:			
4 Heater hoses / PHH	✓		
Note/Recommendation:			
5 Oil Cooler Hose	✓		
Note/Recommendation:			
6 Rear Heater hose	✓		
Note/Recommendation:			
7 Thermostat	✓		
Note/Recommendation:			
8 Water pump	✓		
Note/Recommendation:			
9 Fan Clutch	✓		



**Torfab**  
 2902 W Marine View Drive  
 Everett, WA 98201  
 (206) 659-8677  
 info@torfab.com  
 www.torfab.com

# Inspection #4487

<b>Note/Recommendation:</b>			
10	Hydro carbon test		
<b>Note/Recommendation:</b>			
11	Pressure check @ 20 PSI	✓	
<b>Note/Recommendation:</b>			
12	Special Notes		
<b>Note/Recommendation:</b>			
<b>Totals</b>		<b>9</b>	<b>1</b>
			<b>0</b>

## Engine

Item	Green	Yellow	Red
1 Valve Cover Gasket	✓		
<b>Note/Recommendation:</b>			
2 Oil Pan Gasket		✓	
<b>Note/Recommendation:</b> <i>Dipstick tube leaking down on lower pan</i>			
3 Crank Seal	✓		
<b>Note/Recommendation:</b>			
4 Timing / Oil pump cover	✓		
<b>Note/Recommendation:</b>			
5 Rear main	✓		
<b>Note/Recommendation:</b>			
6 Vacuum routing	✓		
<b>Note/Recommendation:</b>			
7 Emissions status/Engine codes	✓		
<b>Note/Recommendation:</b>			
8 Belts	✓		
<b>Note/Recommendation:</b>			
9 ACC Bearings	✓		



**Torfab**  
 2902 W Marine View Drive  
 Everett, WA 98201  
 (206) 659-8677  
 info@torfab.com  
 www.torfab.com

# Inspection #4487

<b>Note/Recommendation:</b>			
10	Power Steering pump/Engine acc	✓	
<b>Note/Recommendation:</b>			
11	Battery / Cables	✓	
<b>Note/Recommendation:</b>			
12	Sensors / leaks	✓	
<b>Note/Recommendation:</b>			
13	Intake hoses	✓	
<b>Note/Recommendation:</b>			
14	Oil level		
<b>Note/Recommendation:</b>			
15	Air Filter	✓	
<b>Note/Recommendation:</b>			
16	Notes		
<b>Note/Recommendation:</b>			
17	Timing Belt	✓	
<b>Note/Recommendation:</b>			
18			
<b>Note/Recommendation:</b>			
<b>Totals</b>		<b>14</b>	<b>1</b>
			<b>0</b>

## Brakes

Item	Green	Yellow	Red
1 Master Cylinder	✓		
<b>Note/Recommendation:</b>			
2 Booster	✓		
<b>Note/Recommendation:</b>			
3 Brake hose condition	✓		



**Torfab**  
 2902 W Marine View Drive  
 Everett, WA 98201  
 (206) 659-8677  
 info@torfab.com  
 www.torfab.com

# Inspection #4487

<b>Note/Recommendation:</b>			
4	Front calipers	✓	
<b>Note/Recommendation:</b>			
5	Rear calipers	✓	
<b>Note/Recommendation:</b>			
6	Front pads	✓	
<b>Note/Recommendation: 10mm</b>			
7	Rear pads / shoes	✓	
<b>Note/Recommendation: 8mm</b>			
8	Front rotors	✓	
<b>Note/Recommendation:</b>			
9	Rear rotors	✓	
<b>Note/Recommendation:</b>			
10	E-brake cable and shoes	✓	
<b>Note/Recommendation:</b>			
11	Special notes		
<b>Note/Recommendation:</b>			
<b>Totals</b>		<b>10</b>	<b>0</b>

## Drive Train

Item	Green	Yellow	Red
1 Clutch			
<b>Note/Recommendation:</b>			
2 Clutch Master			
<b>Note/Recommendation:</b>			
3 Clutch Slave			
<b>Note/Recommendation:</b>			
4 Transmission condition, leaks, etc	✓		



Torfab  
 2902 W Marine View Drive  
 Everett, WA 98201  
 (206) 659-8677  
 info@torfab.com  
 www.torfab.com

# Inspection #4487

<b>Note/Recommendation:</b>			
5	T-case condition, leaks, etc	✓	
<b>Note/Recommendation:</b>			
6	T-case output bearings/seals	✓	
<b>Note/Recommendation:</b>			
7	Drive line splines / U-Joints	✓	
<b>Note/Recommendation:</b>			
8	Knuckles / CV Shaft	✓	
<b>Note/Recommendation:</b>			
9	Tire condition and age	✓	
<b>Note/Recommendation:</b>			
10	Wheel bearings	✓	
<b>Note/Recommendation:</b>			
11	Shocks / Shock bushings	✓	
<b>Note/Recommendation:</b>			
12	Suspension bushings	✓	
<b>Note/Recommendation:</b>			
13	Front axle fluid/Front pinion seal	✓	
<b>Note/Recommendation:</b>			
14	Rear axle fluid/ Rear pinion seal	✓	
<b>Note/Recommendation:</b>			
15	Steering box or rack	✓	
<b>Note/Recommendation:</b>			
16	Drive flange or Locking hub condition		✓
<b>Note/Recommendation: <i>Slight play</i></b>			
17	Transmission Fluid condition	✓	
<b>Note/Recommendation:</b>			
18	Tie rod ends	✓	



**Torfab**  
2902 W Marine View Drive  
Everett, WA 98201  
(206) 659-8677  
info@torfab.com  
www.torfab.com

# Inspection #4487

<b>Note/Recommendation:</b>			
19	Special notes		
<b>Note/Recommendation:</b>			
<b>Totals</b>		<b>14</b>	<b>1</b>
		<b>0</b>	