

Parts

	#
Used-Air Tube	1
Cap	1
Rotor	1
Spark Plug	6
Ignition Wire Set	1
Fuel Filter	1
Fuel Pump	1
Pump Strainer	1
Plenum Gasket	1
Throttle Body Gasket	1
OEM-Throttle Position Sensor	1
Marine Batter Terminal Set	1
Oil Filter	1
Oil, Full Syn 10w30	8.5
Fuel	
Oxygen Sensor	2
Aftermarket Window Regulator	1
Shifter Bushing	2

Labor

Time

Sublet-Ultrasonic Cleaning/Testing Fuel Injectors	
Sublet-Exhaust Pipe Weld In	
Sublet-Labor and Parts, AC Repair, Replace Evaporator, Vac/Charge	
Major Tuneup	5.00
including valve lash adjustment	
clean throttle body, set tps while off	0.90
Replace Fuel Pump and Sock Strainer	4.50
R&R Fuel Injectors	3.10
Remove Clogged and Broken Cat Converters	0.60
Replace Oxygen Sensors	1.40
<i>had to cut rusted nuts off</i>	
Remove Distributor and Reset Timing	2.10
truck was set to run at 32 degrees advance	
Adjust Driver Door Handle	0.40
Replace Window Regulator	0.60
4th screw wasn't installed causing misalignment and wear	
Repair Passenger Mirror	0.75
plastic weld mounts for hangers	
Replace Shifter Bushings	0.70