



## CAMELBACK COLLISION CENTER

Toyota and Honda Certified Repair Facility .. Now  
featuring "AsTech" Diagnostic- Vehicle- Scanning  
for vehicle safety!

4635 N 7TH ST, PHOENIX, AZ 85014

Phone: (602) 266-0197

FAX: (602) 230-9114

Workfile ID: APUWP453  
PartsShare: 5NCDN6  
Federal ID: 86-0607143

### Supplement of Record 2 with Summary

#### RO Number: 815564A

Written By: Daniel Rognstad, 4/6/2020 2:30:47 PM  
Adjuster: Andrews, Lane, (800) 531-8722 x32105 Business

Insured:	GROVE, ALISON	Policy #:	006577585	Claim #:	006577585000000011001
Type of Loss:	Collision	Date of Loss:	3/12/2020 10:00 AM	Days to Repair:	13
Point of Impact:	15 Total Loss				

<b>Owner:</b>	<b>Inspection Location:</b>	<b>Insurance Company:</b>
GROVE, ALISON	CAMELBACK COLLISION CENTER	USAA CASUALTY INSURANCE COMPANY
4601 N 49TH PL	4635 N 7TH ST	UNIT 1555
PHOENIX, AZ 85018	PHOENIX, AZ 85014	SAN ANTONIO
(602) 761-0290 Cell	Repair Facility	
(602) 761-0290 Evening	(602) 266-0197 Business	

### VEHICLE

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

VIN:	JTEHT05J772113272	Interior Color:	Gray	Mileage In:	116,231	Vehicle Out:
License:	alm4343	Exterior Color:	Silver	Mileage Out:		
State:	AZ	Production Date:	4/2007	Condition:	Good	Job #:

#### TRANSMISSION

Automatic Transmission  
Overdrive  
4 Wheel Drive

#### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Heated Mirrors  
Power Driver Seat  
Power Passenger Seat

#### DECOR

Dual Mirrors  
Body Side Moldings

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Alarm  
Message Center  
Steering Wheel Touch Controls  
Rear Window Wiper  
Telescopic Wheel  
Climate Control  
Dual Air Condition  
Navigation System  
Backup Camera  
Home Link

Search/Seek  
Cassette  
Premium Radio  
Satellite Radio  
CD Changer/Stacker

#### SAFETY

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control  
Front Side Impact Air Bags  
Head/Curtain Air Bags  
Hands Free Device  
Positraction

Reclining/Lounge Seats  
Leather Seats  
Heated Seats  
3rd Row Seat

#### WHEELS

Aluminum/Alloy Wheels  
Locking Wheels

#### PAINT

Clear Coat Paint  
Metallic Paint

#### OTHER

Fog Lamps  
Rear Spoiler  
California Emissions

#### TRUCK

Rear Step Bumper

## Supplement of Record 2 with Summary

---

### RO Number: 815564A

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

Privacy Glass

Console/Storage

Overhead Console

#### CONVENIENCE

#### RADIO

AM Radio

FM Radio

Stereo

#### ROOF

Luggage/Roof Rack

Electric Glass Sunroof

#### SEATS

Trailer Hitch

Trailer Package

Running Boards/Side Steps

## Supplement of Record 2 with Summary

**RO Number: 815564A**

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	<b>INFORMATION LABELS</b>						
2	S02	Rpl information labels				0.3	
3	S02	Repl Emission label all	1129850363	1	1.81	Incl.	
4	S02	Repl Vacuum diagram	1779250044	1	1.78	Incl.	
5	S02	Repl Caution label AC service all	8872360050	1	11.16	Incl.	
6	<b>FRONT BUMPER</b>						
7		O/H front bumper				1.2	
8	**	Repl A/M KEYSIQ Bumper cover	5211960918	1	241.00	Incl.	2.6
9		Add for Clear Coat					1.0
10	S02	Repl Impact pad	5261160020	1	73.90	Incl.	
11	**	S02 Repl Opt OEM Impact bar	5202160120	1	186.00	Incl.	
12	S02	Repl Bumper cover bolt	9010906330	2	2.58		
13	<b>GRILLE</b>						
14		Repl Grille	5310160360	1	424.71	Incl.	
15		Repl Filler panel	5250660061	1	110.07	0.5	1.0
16	S02	Repl RT Panel extn	5390360080	1	79.53	0.2	0.2
17	S02	Repl LT Panel extn	5390460010	1	79.53	0.2	0.2
18	<b>FRONT LAMPS</b>						
19	**	Repl A/M RT Headlamp assy	SEE FOOTNOTE	1	<u>254.00</u>	Incl.	
		Note: Keystone online					
20	**	Repl A/M LT Headlamp assy	SEE FOOTNOTE	1	<u>254.00</u>	Incl.	
21	<b>RADIATOR SUPPORT</b>						
22	S02	Refinish Components					1.5
23	S02	Repl Radiator support	5320160180	1	768.42 s	8.5	Incl.
24	S02	Aim headlamps				0.5	
25	S02	Repl Lock support	5320960091	1	73.11	0.4	
26	<b>COOLING</b>						
27	**	S02 Repl A/M Radiator assy	1640050290	1	247.00 m	Incl.	
28		S02 Repl Fan blade	1636150170	1	194.24 m	Incl.	
29		S02 Repl Shroud	1671150090	1	146.02 m	0.8	
30	*	S02 Repl LKQ Clutch +25%	1621050102	1	50.00 m	<u>1.3</u> M	
31	**	S02 Repl A/M Trans cooler	3291060130	1	262.00 m	1.0	
32	<b>AIR CONDITIONER &amp; HEATER</b>						
33		Repl AC Service evacuate & recharge		1	m	1.4 M	
34		Repl AC Service refrigerant recovery		1	m	0.4 M	
35	**	S02 Repl A/M Condenser assy	8846060903	1	155.00 m	Incl.	
36		S02 Repl AC line at evaporator, front	8872660531	1	139.83 m	Incl.	
37		S02 Repl AC line to condenser	8871560112	1	63.51 m	Incl.	
38		S02 Repl AC line from condenser	8872660462	1	85.90 m	Incl.	
39	#	S02 Subl AC line pigtail +25%		1	181.25 X		
40	<b>HOOD</b>						
41	S02	Repl Hood (HSS)	5330160510	1	759.54	1.6	3.2
42	S02	Add for Underside(Complete)					1.6

## Supplement of Record 2 with Summary

### RO Number: 815564A

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

43		S02		Add for Clear Coat					0.3
44		S01	Repl	Lock	5351060210	1	110.16	Incl.	
45	<b>FENDER</b>								
46		S02	Repl	RT Fender w/o flare (HSS)	5380160A50	1	548.12	2.2	2.2
47		S02		Overlap Major Adj. Panel					-0.4
48		S02		Add for Edging					0.5
49		S02		Add for Clear Coat					0.1
50		S02		Deduct for Overlap				-0.3	
51	*		Rpr	LT Fender w/o flare (HSS)				<u>3.0</u>	2.2
52				Overlap Major Adj. Panel					-0.4
53				Add for Edging					0.5
54	**	S02	Repl	Opt OEM RT Fender liner	5387560021	1	94.00	Incl.	
55		S02	R&I	RT Body side mldg medium gray				0.5	
56		S02	R&I	LT Body side mldg medium gray				0.5	
57	#	S02	Repl	Clean and retape moldings		1	10.00	0.6	
58		S02	Repl	RT Body side mldg fastener	9046712073	3	8.37		
59		S02	Repl	LT Body side mldg fastener	9046712073	3	8.37		
60		S02	Repl	RT Body side mldg clip	9018906211	3	3.54		
61		S02	Repl	LT Body side mldg clip	9018906211	3	3.54		
62		S02	Repl	RT Fender liner retainer	5387960010	6	8.10		
63	*	S02	Rpr	LT Apron panel				<u>4.5</u>	<u>1.0</u>
64		S02		Overlap Major Non-Adj. Panel					-0.2
65	*	S02	Rpr	RT Apron panel				<u>12.5</u>	1.5
66		S02		Overlap Major Non-Adj. Panel					-0.2
67	<b>FRAME</b>								
68	*	S02	Rpr	Frame assy w/o height cntrl (HSS)				<u>4.5</u>	<u>0.5</u>
69	*	S02	Repl	<u>RT Frame assy cushions</u>	1111111111	2	<u>30.00</u>		
70	*	S02	Repl	<u>RT Frame assy bolt</u>	1111111111	1	<u>5.00</u>		
71	*	S02	Repl	<u>LT Frame assy bolt</u>	1111111111	1	<u>5.00</u>		
72	*	S02	Repl	<u>LKQ Hitch Assy +25%</u>	5120760010	1	<u>312.50</u>	<u>1.0</u>	
73	<b>ELECTRICAL</b>								
74		S02	R&I	Antenna assy			m	1.0	
75		S02	R&I	Battery standard			m	Incl.	
76		S02	Repl	Cover upper	8267760051	1	57.29		
77		S02	Repl	Cover lower	8267460010	1	69.73		
78	<b>ENGINE / TRANSAXLE</b>								
79		S02	R&I	Air cleaner assy			m	0.5	
80		S02	Repl	Hose	1787550330	1	520.23		
81	*	S02	R&I	Engine cover				<u>0.4</u>	
82		S02	Repl	Oil filter	90915YZZD3	1	5.41 m	0.5	
83	<b>WINDSHIELD</b>								
84		S02	Repl	Reservoir assy	8532560140	1	134.12	0.6	
85	<b>FRONT DOOR</b>								
86			Blnd	RT Door shell w/molding (HSS)					1.0

## Supplement of Record 2 with Summary

### RO Number: 815564A

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

87		R&I	RT Belt w'strip				0.3	
88		R&I	RT Body side mldg medium gray				0.5	
89		R&I	RT Mirror assy gray				0.4	
90		R&I	RT Handle, outside medium gray				0.4	
91		R&I	RT R&I trim panel				0.4	
92	<b>QUARTER PANEL</b>							
93	*	S02	Rpr LT Lower qtr panel w/o molding swing glass				<u>4.0</u>	<u>1.5</u>
94			Add for Edging					0.3
95		R&I	LT Body side mldg front medium gray				0.3	
96		S02	Repl LT Body side mldg clip front	9046712073	2	5.58		
97		S02	Repl LT Body side mldg clip rear	9046712072	2	4.66		
98	<b>TAIL GATE</b>							
99	*	S02	Repl LKQ Tail gate from 12/98 (HSS) +25%	6506160231	1	<u>687.50</u>	<u>2.0</u>	<u>3.0</u>
100		S02	Overlap Major Non-Adj. Panel					-0.2
101		S02	Clear Coat					2.5
102		R&I	Handle, outside				Incl.	
103	<b>REAR LAMPS</b>							
104	*	R&I	LT Tail lamp assy				<u>Incl.</u>	
105	*	R&I	RT Tail lamp assy				<u>Incl.</u>	
106	*	R&I	LT Tail lamp assy				<u>0.2</u>	
107	<b>REAR BUMPER</b>							
108		S02	O/H rear bumper				1.5	
109		S02	R&I R&I bumper assy				Incl.	
			Note: Drop for refinish					
110	**	S02	Repl Opt OEM Impact pad	5230960010	1	334.74	Incl.	
111		S02	Repl Lower reinf	5217160070	1	65.02	Incl.	
112	<b>MISCELLANEOUS OPERATIONS</b>							
113			Repl Cover car/bag		1		0.2	
114	#		Rpr Disconnect Battery & Reset Electrical Components				0.3	
115	#		Rpr Disable Air Bag				0.3	M
116	#		Repl Corrosion Protection		1	5.00		
117	#		Repl Caulk/Seam Sealer		1	15.00		
118	#		Repl Flex additive		1	6.00		
119	#		Rpr Pull - Unibody / Full Frame				2.0	F
120	#		Subl Weld Thru Primer		1	5.00	X	
121	#		Rpr Setup & Measure				1.5	
122			OTHER CHARGES					
123	#		E.P.C.		1	3.50		
<b>SUBTOTALS</b>						<b>7,911.37</b>	<b>64.6</b>	<b>27.0</b>

### NOTES

## Supplement of Record 2 with Summary

### RO Number: 815564A

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

Prior Damage Notes:  
none

#### ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					7,721.62
Body Labor	59.2 hrs	@		\$ 52.00 /hr	3,078.40
Paint Labor	27.0 hrs	@		\$ 52.00 /hr	1,404.00
Mechanical Labor	3.4 hrs	@		\$ 95.00 /hr	323.00
Frame Labor	2.0 hrs	@		\$ 52.00 /hr	104.00
Paint Supplies					450.00
Miscellaneous					186.25
Other Charges					3.50
Subtotal					13,270.77
Sales Tax	\$ 8,357.87	@		8.6000 %	718.78
<b>Grand Total</b>					<b>13,989.55</b>
Deductible					1,000.00
<b>CUSTOMER PAY</b>					<b>1,000.00</b>
<b>INSURANCE PAY</b>					<b>12,989.55</b>

## Supplement of Record 2 with Summary

**RO Number: 815564A**

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

### SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
<b>Changed Items</b>							
5		Repl Grille	5310160360	1	-424.71	-0.4	
14	S02	Repl Grille	5310160360	1	424.71	Incl.	
9	**	Repl A/M RT Headlamp assy NOTE: Keystone online	SEE FOOTNOTE	1	<u>-254.00</u>	-0.8	
19	**	S02 Repl A/M RT Headlamp assy NOTE: Keystone online	SEE FOOTNOTE	1	<u>254.00</u>	Incl.	
10	**	Repl A/M LT Headlamp assy	SEE FOOTNOTE	1	<u>-254.00</u>	-0.8	
20	**	S02 Repl A/M LT Headlamp assy	SEE FOOTNOTE	1	<u>254.00</u>	Incl.	
24		S01 Repl Lock	5351060210	1	-110.16	-0.6	
44		S02 Repl Lock	5351060210	1	110.16	Incl.	
46	*	Rpr LT Lower qtr panel w/o molding swing glass			<u>-4.0</u>		-2.4
93	*	S02 Rpr LT Lower qtr panel w/o molding swing glass			<u>4.0</u>		<u>1.5</u>
56		R&I Handle, outside				-0.6	
102		S02 R&I Handle, outside				Incl.	
58	*	R&I LT Tail lamp assy			<u>-0.2</u>		
104	*	S02 R&I LT Tail lamp assy			<u>Incl.</u>		
59	*	R&I RT Tail lamp assy			<u>-0.2</u>		
105	*	S02 R&I RT Tail lamp assy			<u>Incl.</u>		
62	*	R&I R&I bumper assy			<u>-0.5</u>		
109		S02 R&I R&I bumper assy NOTE: Drop for refinish				Incl.	
<b>Deleted Items</b>							
7		Repl Grille	5310160360	1	-424.71	Incl.	
12		Repl RT Signal lamp assy	8151060500	1	-115.50	Incl.	
13		Repl LT Signal lamp assy	8152060370	1	-115.50	-0.3	
14	<b>RADIATOR SUPPORT</b>						
15		Repl Upper tie bar	5320560040	1	-181.66 s	-2.0	-0.6
16	<b>COOLING</b>						
17		R&I Radiator assy				m -1.5	
19		R&I Condenser assy				m -1.5	
23	**	Repl A/M KEYSIQ Hood (HSS)	5330160510	1	-646.00	-1.6	-3.2
24		Add for Underside(Complete)					-1.6
27	**	Repl A/M RT Fender w/o flare (HSS)	5380160A50	1	<u>-348.00</u>	-2.2	-2.2
28		NOTE: Keystone Overlap Major Adj. Panel					0.4
29		Add for Edging					-0.5
30		Deduct for Overlap				0.3	

## Supplement of Record 2 with Summary

### RO Number: 815564A

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

34	<b>ROOF</b>								
35		R&I	LT Side rail assy					-0.6	
36	<b>PILLARS, ROCKER &amp; FLOOR</b>								
37		R&I	LT Step panel					-0.6	
38		R&I	RT Step panel					-0.6	
49		R&I	LT Belt molding					-0.5	
51		R&I	LT Mud guard					-0.3	
52	*	R&I	LT Vent louver					<u>-0.3</u>	
54	*	Rpr	Tail gate from 12/98 (HSS)					<u>-7.0</u>	-2.0
55			Overlap Major Non-Adj. Panel						0.2
56			Clear Coat						-2.5
74	#	Refn	Clear Wrap Left Outer Rail						-0.6
<b>Added Items</b>									
1	<b>INFORMATION LABELS</b>								
2		S02	Rpl information labels					0.3	
3		S02	Repl Emission label all	1129850363	1	1.81		Incl.	
4		S02	Repl Vacuum diagram	1779250044	1	1.78		Incl.	
5		S02	Repl Caution label AC service all	8872360050	1	11.16		Incl.	
10		S02	Repl Impact pad	5261160020	1	73.90		Incl.	
11	**	S02	Repl Opt OEM Impact bar	5202160120	1	186.00		Incl.	
12		S02	Repl Bumper cover bolt	9010906330	2	2.58			
16		S02	Repl RT Panel extn	5390360080	1	79.53		0.2	0.2
17		S02	Repl LT Panel extn	5390460010	1	79.53		0.2	0.2
21	<b>RADIATOR SUPPORT</b>								
22		S02	Refinish Components						1.5
23		S02	Repl Radiator support	5320160180	1	768.42 s		8.5	Incl.
24		S02	Aim headlamps					0.5	
25		S02	Repl Lock support	5320960091	1	73.11		0.4	
26	<b>COOLING</b>								
27	**	S02	Repl A/M Radiator assy	1640050290	1	247.00 m		Incl.	
28		S02	Repl Fan blade	1636150170	1	194.24 m		Incl.	
29		S02	Repl Shroud	1671150090	1	146.02 m		0.8	
30	*	S02	Repl LKQ Clutch +25%	1621050102	1	50.00 m		<u>1.3</u> M	
31	**	S02	Repl A/M Trans cooler	3291060130	1	262.00 m		1.0	
35	**	S02	Repl A/M Condenser assy	8846060903	1	155.00 m		Incl.	
36		S02	Repl AC line at evaporator, front	8872660531	1	139.83 m		Incl.	
37		S02	Repl AC line to condenser	8871560112	1	63.51 m		Incl.	
38		S02	Repl AC line from condenser	8872660462	1	85.90 m		Incl.	
39	#	S02	Subl AC line pigtail +25%		1	181.25 X			
41		S02	Repl Hood (HSS)	5330160510	1	759.54		1.6	3.2
42		S02	Add for Underside(Complete)						1.6
43		S02	Add for Clear Coat						0.3
46		S02	Repl RT Fender w/o flare (HSS)	5380160A50	1	548.12		2.2	2.2
47		S02	Overlap Major Adj. Panel						-0.4
48		S02	Add for Edging						0.5



## Supplement of Record 2 with Summary

### RO Number: 815564A

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

49		S02		Add for Clear Coat					0.1
50		S02		Deduct for Overlap				-0.3	
54	**	S02	Repl	Opt OEM RT Fender liner	5387560021	1	94.00	Incl.	
55		S02	R&I	RT Body side mldg medium gray				0.5	
56		S02	R&I	LT Body side mldg medium gray				0.5	
57	#	S02	Repl	Clean and retape moldings		1	10.00	0.6	
58		S02	Repl	RT Body side mldg fastener	9046712073	3	8.37		
59		S02	Repl	LT Body side mldg fastener	9046712073	3	8.37		
60		S02	Repl	RT Body side mldg clip	9018906211	3	3.54		
61		S02	Repl	LT Body side mldg clip	9018906211	3	3.54		
62		S02	Repl	RT Fender liner retainer	5387960010	6	8.10		
63	*	S02	Rpr	LT Apron panel				<u>4.5</u>	<u>1.0</u>
64		S02		Overlap Major Non-Adj. Panel					-0.2
65	*	S02	Rpr	RT Apron panel				<u>12.5</u>	1.5
66		S02		Overlap Major Non-Adj. Panel					-0.2
67	<b>FRAME</b>								
68	*	S02	Rpr	Frame assy w/o height cntrl (HSS)				<u>4.5</u>	<u>0.5</u>
69	*	S02	Repl	<u>RT Frame assy cushions</u>	1111111111	2	<u>30.00</u>		
70	*	S02	Repl	<u>RT Frame assy bolt</u>	1111111111	1	<u>5.00</u>		
71	*	S02	Repl	<u>LT Frame assy bolt</u>	1111111111	1	<u>5.00</u>		
72	*	S02	Repl	<u>LKQ Hitch Assy +25%</u>	5120760010	1	<u>312.50</u>	<u>1.0</u>	
73	<b>ELECTRICAL</b>								
74		S02	R&I	Antenna assy			m	1.0	
75		S02	R&I	Battery standard			m	Incl.	
76		S02	Repl	Cover upper	8267760051	1	57.29		
77		S02	Repl	Cover lower	8267460010	1	69.73		
78	<b>ENGINE / TRANSAXLE</b>								
79		S02	R&I	Air cleaner assy			m	0.5	
80		S02	Repl	Hose	1787550330	1	520.23		
81	*	S02	R&I	Engine cover				<u>0.4</u>	
82		S02	Repl	Oil filter	90915YZZD3	1	5.41 m	0.5	
83	<b>WINDSHIELD</b>								
84		S02	Repl	Reservoir assy	8532560140	1	134.12	0.6	
96		S02	Repl	LT Body side mldg clip front	9046712073	2	5.58		
97		S02	Repl	LT Body side mldg clip rear	9046712072	2	4.66		
99	*	S02	Repl	LKQ Tail gate from 12/98 (HSS) +25%	6506160231	1	<u>687.50</u>	<u>2.0</u>	<u>3.0</u>
100		S02		Overlap Major Non-Adj. Panel					-0.2
101		S02		Clear Coat					2.5
108		S02		O/H rear bumper				1.5	
110	**	S02	Repl	Opt OEM Impact pad	5230960010	1	334.74	Incl.	
111		S02	Repl	Lower reinf	5217160070	1	65.02	Incl.	
<b>SUBTOTALS</b>							<b>4,651.56</b>	<b>24.5</b>	<b>3.8</b>

## Supplement of Record 2 with Summary

**RO Number: 815564A**

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

### TOTALS SUMMARY

Category	Basis			Rate	Cost \$
Parts					4,470.31
Body Labor	23.8 hrs	@		\$ 52.00 /hr	1,237.60
Paint Labor	3.8 hrs	@		\$ 52.00 /hr	197.60
Mechanical Labor	1.3 hrs	@		\$ 95.00 /hr	123.50
Additional Supplement Labor					-31.20
Paint Supplies	4.0 hrs	@		\$ 32.00 /hr	128.00
Additional Supplement Materials/Supplies					-128.00
Miscellaneous					181.25
Subtotal					6,179.06
Sales Tax	\$ 4,651.56	@		8.6000 %	400.03
Additional Supplement Taxes					0.01
<b>Total Supplement Amount</b>					<b>6,579.10</b>
<b>NET COST OF SUPPLEMENT</b>					<b>6,579.10</b>

### CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	7,410.45	Warren Session
Supplement S01	0.00	Warren Session
Supplement S02	6,579.10	Daniel Rognstad
<b>Job Total:</b>	<b>\$ 13,989.55</b>	
<b>CUSTOMER PAY:</b>	<b>\$ 1,000.00</b>	
<b>INSURANCE PAY:</b>	<b>\$ 12,989.55</b>	

This damage report is based upon our detailed inspection of your vehicle and does not include repairs other than itemized above. Occasionally, additional damage will be discovered once the work is opened up and additional repairs will be required.

\*\*\* FULL PAYMENT IS DUE BEFORE VEHICLE IS RELEASED. \*\*\*

**RO Number: 815564A**

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

Please Present A Copy Of This Estimate To A Repair Facility Of Your Choice

\*USAA Subsidiaries include: United Services Automobile Association(USAA), USAA Casualty Insurance Company(CIC), USAA General Indemnity Company(GIC) USAA County Mutual Insurance(CMI) and Garrison Property Casualty Insurance Company. Garrison Property and Casualty Insurance Company, a subsidiary of USAA Casualty Insurance Company, is authorized to use the USAA logo, a registered trademark of United Services Automobile Association.

This is not an authorization to repair. Failing to present this estimate to the repairing garage before repair may result in additional expenses to you. A USAA appraiser must authorize any supplement to this estimate. Repairs to this vehicle may require specific welding equipment as recommended by the manufacturer.

If alternative quality replacement parts have been included in this appraisal, the source for these parts has also been disclosed. If alternative quality replacement parts as listed on the appraisal are ultimately used in the repair of your vehicle, the warranty on such parts will be equal to, or greater than, the parts being replaced, as stated in USAA's limited parts warranty. USAA warrants that the parts used on your vehicle will be of like kind and quality, function, fit, safety and corrosion protection as the part or parts they replace. USAA identifies certified and validated parts for sheet metal replacement parts.

FOR YOUR PROTECTION ARIZONA LAW REQUIRES THE FOLLOWING STATEMENT TO APPEAR ON THIS FORM. ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS IS SUBJECT TO CRIMINAL AND CIVIL PENALTIES.

Estimate calculated using a preset user threshold amount for the paint and material cost.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

**RO Number: 815564A**

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide AEM8415, CCC Data Date 04/01/2020, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2020 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

**SYMBOLS FOLLOWING PART PRICE:**

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

**SYMBOLS FOLLOWING LABOR:**

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

**OTHER SYMBOLS AND ABBREVIATIONS:**

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Supplement of Record 2 with Summary****RO Number: 815564A**

2007 TOYO Land Cruiser 4WD 4D UTV 8-4.7L Gasoline EFI Silver

**PARTS SUPPLIER LIST**

<b>Line</b>	<b>Supplier</b>	<b>Description</b>	<b>Price</b>
8	Keystone-USAA-B-North Las Vegas 3370 E LONE MOUNTAIN RD STE D NORTH LAS VEGAS NV 89081 (800) 551-5331 (702) 789-4000	#TO1000267 A/M KEYSIQ Bumper cover	\$ 241.00
11	Keystone 5670 S. 32nd Street Phoenix AZ 85040 (602) 272-5911	#TO1006192OE Opt OEM Impact bar Quote: 546625252 Expires: 05/15/20	\$ 186.00
27	Performance Radiator 2505 Candelaria Rd NE Albuquerque NM 87107 (505) 881-8059	#2835 A/M Radiator assy Quote: 9458020 Expires: 04/01/20	\$ 247.00
30	LKQ Corp 3024 South 40th Street Phoenix AZ 85040 (602) 437-0194	#~214679919 LKQ Clutch +25% Fan Clutch 4.7,AUTO,4X2 8 CYL (2UZFE ENGINE),S#\$PC271 Quote: 546630405 Expires: 05/15/20	\$ 40.00
31	1-800-Radiator 2401 W.PHELPS RD. SUITE E Phoenix AZ 85023 (602) 861-3441	#24000136AP A/M Trans cooler Quote: 20659217 Expires: 04/14/20	\$ 262.00
35	Performance Radiator 21 North 20th St Phoenix AZ 85034 (800) 949-1191	#3376 A/M Condenser assy Quote: 9359249 Expires: 03/27/20	\$ 155.00
54	Keystone 5670 S. 32nd Street Phoenix AZ 85040 (602) 272-5911	#TO1249114OE Opt OEM RT Fender liner Quote: 546633074 Expires: 05/15/20	\$ 94.00
110	Platinum Auto Trends - CA 14434 BEST AVENUE SANTA FE SPRINGS CA 90670 (562) 229-7691	#GEU3357W-12109 Opt OEM Impact pad Quote: 619330311 Expires: 04/07/20	\$ 334.74