

NTB 847460 HWY 79
HUTTO, TX 78634

Phone Number: 512-846-1086

Customer:	Date: 9/10/2019 9:30 AM
Company:	VIN
License No:	Technician:
Odometer:	Order No.:

VEHICLE ALIGNMENT REPORT
TOYOTA, 2016, LAND CRUISER All Models

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3.1°	2.3°	3.8°	3.0°
		Right	3.0°	2.3°	3.8°	3.0°
	Camber	Left	-0.2°	-0.4°	1.2°	-0.1°
		Right	0.0°	-0.4°	1.2°	0.0°
	Toe	Left	0.25°	0.00°	0.20°	0.05°
		Right	-0.05°	0.00°	0.20°	0.05°
		Total	0.20°	0.05°	0.40°	0.10°
Rear	Camber	Left	-0.5°	----	----	-0.5°
		Right	-0.4°	----	----	-0.4°
	Toe	Left	0.00°	----	----	0.05°
		Right	0.10°	----	----	0.10°
		Total	0.10°	----	----	0.15°
	Thrust Angle		0.1°	----	----	0.0°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13.1°	11.8°	13.3°	13.1°
	Right		12.7°	11.8°	13.3°	12.7°
Included Angle	Left		12.9°	----	----	13.0°
	Right		12.7°	----	----	12.7°
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	33.6°	36.6°	----
	Right		----	33.6°	36.6°	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-0.1"	----	----	-0.2"
	Rear		0.1"	----	----	0.1"
Track Width Diff.			4.4"			4.4"
Wheel Base Diff.			-0.2"			-0.2"
Front Ride Height	Left		0.0"	3.3"	3.3"	0.0"
	Right		0.0"	3.3"	3.3"	0.0"
Rear Ride Height	Left		0.0"	3.2"	3.2"	0.0"
	Right		0.0"	3.2"	3.2"	0.0"
Frame Angle						----