



# Vehicle Inspection Report

## Important Information

OFFICIAL RECORD WHICH MUST BE PRESENTED IF THE VEHICLE IS TO BE REINSPECTED. IF LOST, A RECORD MAY BE OBTAINED FROM ANY INSPECTION FACILITY OR [state.nj.us/mvc/Inspections/VIRReprint.html](http://state.nj.us/mvc/Inspections/VIRReprint.html).

Vehicle must pass inspection by 12/31/2020, or it may be subjected to a fine(s) and/or registration suspension. THIS DOCUMENT FOR USE ON REINSPECTION. Questions? Visit NJINSPECTIONS.COM or call the Motorist at 1-888-NJMOTOR.

FACILITY INFO		VEHICLE INFO	CONTROL INFO	
Mays Landing		VIN: JT3HJ85J8V0184115	Certificate:	CIF000033202034727027
1477 19th St.		Plate: H310WC NJ	Software Version:	20190617-01/01
Mays Landing, NJ 08330		Veh. Type:	Date:	12/12/2020
888-656-6867		Year: 1997	Time:	07:30:27 AM
Facility ID: CIF000033		Make: TOYOTA	Inspection Type:	INITIAL IMC
Workstation ID: CL150204		Model: LAND CRUISER	Sticker#:	C6789588
		Odometer: 228984		
		Fuel Type: GASO		
		GVWR: 6470		

**FINAL RESULT: FAIL Overall Safety Results: N/A Overall Emissions Result: FAIL Credentials: PASS**

This test was performed in conformance with section 207(b) of the Federal Clean Air Act and the Inspection Sticker Date is 11/30/2020.

## Primary Emission Test Performed: OBD - FAIL

### OBD SYSTEM - DIAGNOSTIC RESULTS

Bulb Check:	PASS	OBD Connector:	PASS	MIL Command Status:	PASS
Check Engine Light On:	FAIL	OBD Communications:	PASS	Overall Readiness Result:	FAIL

### OBD SYSTEM - READINESS STATUS

Engine Misfire	READY	Catalytic Converters	NOT READY	A/C Refrigerant	UNSUPPORTED
Fuel System	READY	Heated Catalytic Converters	UNSUPPORTED	Oxygen Sensors	READY
Comprehensive Component	READY	Evaporative System	UNSUPPORTED	Oxygen Sensors - Heaters	NOT READY
		Secondary Air Injection	UNSUPPORTED	EGR Systems	NOT READY

### OBD SYSTEM - DIAGNOSTIC TROUBLE CODES PRESENT:

Total # of codes Present:	0	Individual Codes Present:	N/A
---------------------------	---	---------------------------	-----

## Secondary Emissions Test(s) Performed:

TEST	RESULT:
Gas Cap	PASS
Tampering	PASS
Visible Smoke	PASS
Liquid Leak	PASS
Indicator Light	FAIL
Misc. Emissions	PASS

## EXPLANATION:

Based on information obtained from the On-Board Diagnostic (OBD) system, this vehicle has failed due to a problem with the pollution control system. To continue with the inspection process, the pollution control system should be repaired and the vehicle reinspected. Fault Codes stored on the OBD system are listed above to assist in repairing the vehicle.

Based on information obtained from the On-Board Diagnostic (OBD) system, the system is not ready to determine the status of the pollution control system on this vehicle. To continue with the inspection process, the vehicle's OBD system must be ready for testing upon reinspection. See the vehicle owner's manual for information on "OBD/Readiness Driving Procedures" or contact your vehicle service provider.