

2000 Toyota Land Cruiser



This vehicle is in good running and driving condition with a few things of note.

NOTE: The vehicle was very dirty at time of inspection which can hide blemishes.

Exterior

The front end and left door have general misalignment to body panels, see pictures. This vehicle has excessive scratches, chips, dings, corrosion and scuffs all over the exterior. The paint shows bubbling paint from rust, around windows and on rear hatch door. See pics. The driver fender and driver door do not show VIN numbers and show poor repaint. There has been some sort of repairs to the whole front end, driver's fender and driver's door. The underside of the vehicle shows signs of major rust. Metal possibly will be needed to fix these areas. The rockers have damage to the pinch weld behind passenger side wheel well and is rusting. See pics. The door mirror housings have miscellaneous scratches. The front bumper shows signs of repaint with several imperfections. The side moldings show areas which are worn dull. The windshield has miscellaneous stone chips. The chrome is pitted and wearing due to age. The engine shows active oil leaks. The engine should be pressure washed off and rechecked to verify source of the leak or all leaks. The exhaust shows

some surface rust throughout, but at this time has no leaks and sounds good. All accessible fluids are at specified levels and look clean. All exterior lighting is functioning. The three matching wheels and tires are in good shape. The passenger side rear is the spare and tire is mismatched in both size and branding. The spare also shows heavy dry rot.

Interior

The steering wheel shows wear and tear as seen in pics. Normal for mileage. The front seats show moderate to heavy wear. The rear seats have some staining and indentations from child seats or seat belts when laid down. The rear seats mount pocket show rust. The inner door panels and interior trim show moderate wear. See pics. The wood laminate is coming apart in several spots. The carpet shows moderate wear from use. The carpet also shows heavy staining. The floor mats show heavy wear. The floor mats should be replaced. The headliner shows miscellaneous smudge marks and stains from normal use. The windows, mirrors, seats, radio, heating and a/c etc. are all in working order. When entering the vehicle there was no sign of foul odors or smoke. The interior lighting and instrumentation is all in working order.

Test drive

Found no issues on the test drive. Vehicle had good power delivery and transmission shifted without issue. The brakes were firm with no pulsating . No abnormal noises or vibrations. No fault codes stored. Vehicle does have oil leaks that need diagnosis. The engine had visible burning oil smoke coming from the front wheel wells, further diagnosis is needed. Please see photos and below for more info.

| Vehicle Info | |
|--------------------------------|--|
| Year - 2000 | |
| Make - Toyota | |
| Model - Land Cruiser | |
| Mileage - 233121 | |
| Transmission - Automatic | |
| VIN Number - jt3ht05j1y0110289 | |
| Interior - Leather | |
| Interior Color - Tan | |
| Body Color - Black | |
| Engine - 8 Cylinder | |
| Drive Type - Four Wheel Drive | |
| Fuel Type - Gas | |

| Exterior | |
|---|---|
| Wiper Blades | ✓ |
| Windshield Washer | ✓ |
| Body Alignment | ✗ |
| Front end and left door have general misalignment to body panels, see pictures. | |
| Scratches | ✗ |
| This vehicle has excessive scratches, chips, dings and scuffs all over the exterior. | |
| Dents | ✓ |
| Paint Condition | ✗ |
| The paint has several spots of bubbling paint from rust. See pics. The driver fender and driver door do not show VIN numbers and show poor repaint. | |

| Mechanical | |
|--|---|
| Air Filter | ✓ |
| Battery Condition | ✓ |
| Charging System | ✓ |
| Cooling Fan Condition | ✓ |
| Radiator Cap Sealing Properly | ✓ |
| Hoses | ✓ |
| Radiator | ✓ |
| Engine Coolant | ✓ |
| Coolant Leaks | ✓ |
| Belts | ✓ |
| Power Steering | ✓ |
| Steering Fluid | ✓ |
| Engine Oil | ✓ |
| Engine Fluid Leaks | ✗ |
| The engine shows active oil leaks. The engine should be pressure washed off and rechecked to verify source of the leak or all leaks. | |
| Transmission Fluid | ✓ |
| Transmission Leaks | ✓ |
| Brake System | ✓ |
| Brake Fluid Leaks | ✓ |
| Transfer Case Leaks | ✓ |
| Differential leaks | ✓ |
| Muffler System | ✗ |
| Exhaust shows some surface rust throughout, but at this time has no leaks and sounds good. | |
| CV Joints and Axles | ✓ |
| Shocks and bushings | ✓ |

| | |
|---|---|
| Body Seals | ✓ |
| Rust | ✗ |
| The underside of the vehicle shows signs of major rust. Metal possibly will be needed to fix these areas. | |
| Exterior Lights | ✓ |
| Sunroof | ✓ |
| Door Mirrors | ✗ |
| The door mirror housings have miscellaneous scratches. | |
| Bumpers | ✗ |
| The front bumper shows signs of repaint with several imperfections. | |
| Side Moldings | ✗ |
| The side moldings show areas which are worn dull. | |
| Frame Damage | ✓ |
| Glass | ✗ |
| The windshield has miscellaneous stone chips. | |
| Body Filler? | ✓ |
| Hood | ✓ |
| Doors | ✓ |
| Floors | ✓ |
| Rockers | ✗ |
| The rockers have damage to the pinch weld behind passenger side wheel well and is rusting. See pics. | |
| Quarter Panels | ✓ |
| Chrome | ✗ |
| The chrome is pitted and wearing due to age. | |

| | |
|--|---|
| Interior | |
| Steering Wheel | ✗ |
| The steering wheel shows wear and tear as seen in pics. Normal for mileage. | |
| Horn | ✓ |
| Cruise Control | ✓ |
| Seat Condition | ✗ |
| The front seats show moderate to heavy wear. The rear seats have some staining and indentations from child seats or seat belts when laid down. | |
| Heated Seats | ✓ |
| Seat Belts | ✓ |
| Clock | ✓ |
| Radio/Navigation | ✓ |
| Inner Door Panels | ✗ |
| The inner door panels show wear consistent with age and mileage. | |
| Power Locks | ✓ |
| Window Switches | ✓ |
| Window Function | ✓ |
| Center Console | ✓ |
| Dash | ✓ |
| Sun Visors | ✓ |
| Dash Lights | ✓ |
| Dash Gauges | ✓ |
| Air Conditioning | ✓ |
| Heater | ✓ |
| Carpet | ✗ |
| The carpet shows moderate wear from use. The carpet also shows heavy staining. | |
| Floor Mats | ✗ |
| The floor mats show heavy wear. The floor mats should be replaced. | |
| Cigarette Use | ✓ |
| Unusual Odors | ✓ |
| Cup Holders | ✓ |
| Headliner | ✗ |
| The headliner shows miscellaneous smudge marks and stains from | |

| | |
|--------------------------|---|
| Ball Joints and Tie Rods | ✓ |
| Modifications | ✓ |

| | |
|---------------------------|---|
| Road Test | |
| Road Test | ✓ |
| Engine Performance | ✓ |
| Transmission performance | ✓ |
| Differential Performance | ✓ |
| Transfer Case Performance | ✓ |
| Wheel Bearing Performance | ✓ |
| Braking Performance | ✓ |
| Suspension Performance | ✓ |
| Steering Performance | ✓ |
| Engine Starting | ✓ |

| | |
|--|--|
| TIRES/WHEELS | |
| Tire Manufacturer | |
| Driver's Front - Falken | |
| Passenger's Front - Falken | |
| Driver's Rear - Falken | |
| Passenger's Rear - Michelin | |
| Tire Size | |
| Driver's Front - 265/75/r16 | |
| Passenger's Front - 265/75/r16 | |
| Driver's Rear - 265/75/r16 | |
| Passenger's Rear - 275/70/r16 | |
| Tire Condition | |
| Driver's Front - No Issues | |
| Passenger's Front - No Issues | |
| Driver's Rear - No Issues | |
| Passenger's Rear - Dry Rot | |
| Wheel Condition | |
| Driver's Front - No Issues | |
| Passenger's Front - No Issues | |
| Driver's Rear - No Issues | |
| Passenger's Rear - Curb Rash, Missing Hubcap/Center Cap, Scratches | |
| Tire Tread | |
| Driver's Front - 8/32 | |
| Passenger's Front - 8/32 | |
| Driver's Rear - 8/32 | |
| Passenger's Rear - 8/32 | |



| |
|--|
| 10/32 OR MORE |
| Tires have plenty of tread! (standard) |
| 8/32 OR MORE |
| Tires have plenty of tread! (low profile) |
| 5/32 TO 7/32 |
| Tires will need replacement soon! |
| 4/32 OR LESS |
| Tires need replacement! |

| | |
|--|---|
| normal use. | |
| Blower Motor | ✓ |
| Interior Trim | ✗ |
| The interior trim shows normal wear consistent with age and mileage. | |
| Inner Trunk | ✓ |

1









LAUNCH

Read Trouble Code

No Fault Code

OK

HOME

PRINT

Vehicle 1

11:07 PM

X-431 Diagon